


# Jamestown Apartments Stream Restoration Project



Construction  
Fall 2006

# Jamestown Apartments Stream Restoration Project



# Lack of Vegetated Buffer




# Existing Erosion Areas



Erosion endangering building foundations




Erosion threatening parking lot integrity



Stream channel  
widened and stream  
slope varied to reduce  
velocities in channel





Stream widened and  
meander established





Paved ditch replace  
with Step Pools and  
Rock Cascade





Log Vane



# Plant Installation



# Trail and Signs



The project is a success. The stream was transformed from an eroding channel with little vegetation...



to a stabilized stream...



with a beautiful native buffer.

